









Subject: RE: Information - mortgage

Please find attached the Gas membrane validation letter associated with the installation of the gas protection measures.

With regards to the 'hot spot' of contamination, I can confirm that this has been delineated, excavated and emplaced on the southern portion of the site. I attach photos showing these works. The emplaced impacted soils will be covered with at least 1.00m of clean imported soils during the landscaping works towards the end of the development. Following this Arc will attend site confirm the cover thickness and recover samples of the imported soils for contamination screening to

confirm their suitability for use in a residential setting. A final validation report will be produced to confirm these works have been carried out in accordance with the remediation statement.

I trust the above ands attached are satisfactory however, if you have any queries, please let me know.

Regards



email: darren.mcgrath@arc-environmental.com web: www.arc-environmental.com

Registered Office: Solum House, Unit 1 Elliott Court, St John's Road, Meadowfield, Durham, DH7 8PN

Registered in England, No. 05539784

This e-mail and any attachments to it are intended only for the party whom they are addressed. They may contain privileged and/or confidential information. If you have received this transmission in error, please notify the sender immediately and delete any digital copies and destroy any paper copies. Although we have taken steps to ensure that this e-mail and any attachments are free from any virus, we advise that in keeping with good computing practice the recipient should ensure that they are actually virus free. No responsibility is accepted by Arc Environmental Ltd for loss or damage arising in any way from receipt or use thereof.

Please consider the environment before printing this e-mail.









