

LOCATION - MILL HILL

STAGE 3 - PLANNING DESIGN ANALYSIS
7 GLENMERE AVENUE, MILL HILL

Aerial image highlighting the development site within the local area.



DMCA ARCHITECTS


SITE - 7 GLENMERE AVENUE

STAGE 3 - PLANNING DESIGN ANALYSIS
7 GLENMERE AVENUE, MILL HILL

Aerial image illustrating the immediate context around the development site



ENVIRONMENTAL ANALYSIS



Front Elevation of 7 Glenmere Avenue



Oblique Street view of 7 Glenmere Avenue



These exterior views demonstrate the front elevation fronting Glenmere Avenue. The existing driveway is very narrow, offering limited width for car occupants to exit a car. The driveway rises steeply to the garage, which is in a poor state of repair. With 6'6" wide doors and an internal width of 7'6", there is insufficient space to park even a modestly sized modern car within the garage.

The existing approach steps are non-compliant with Building Regulations, being too shallow and with inconsistent risers. These were installed to align with the existing driveway slope.

EXISTING VIEWS

Rear Elevation of 7 Glenmere Avenue




Longer View of Rear



These exterior rear views show the proposed location for the new rear extension.

The old flue chimney on this elevation is no longer in use and we intend to remove this as part of the works.



STAGE 3 - PLANNING DESIGN ANALYSIS
7 GLENMERE AVENUE, MILL HILL

NORTH WEST AXONOMETRIC



PROPOSED SCHEME

NORTH WEST AXONOMETRIC



EXISTING PROPERTY

STAGE 3 - PLANNING DESIGN ANALYSIS
7 GLENMERE AVENUE, MILL HILL

NORTH EAST AXONOMETRIC



PROPOSED SCHEME

NORTH EAST AXONOMETRIC



STAGE 3 - PLANNING DESIGN ANALYSIS
7 GLENMERE AVENUE, MILL HILL

SOUTH EAST AXONOMETRIC



PROPOSED SCHEME

STAGE 3 - PLANNING DESIGN ANALYSIS
7 GLENMERE AVENUE, MILL HILL

SOUTH EAST AXONOMETRIC

