13 Willow Park, Upton Lane, Stoke Golding, Nuneaton, Warwickshire CV13 6EU

Our Ref: 222945L-1

3rd January 2023

FAO Paul Willey Rose Builders Limited Riverside House Riverside Avenue East Lawford Essex CO11 1US

Dear Paul

Ongoing Groundwater Monitoring – Former Chambers Bus Garage, Bures

Since issue of the Phase 2 investigation report in June 2022 we have continued to make regular visits to Bures to monitor groundwater levels in BHA to BHD, WS2 and in the additional two monitoring points (BHE and BHG) installed during the geotechnical investigation for piling undertaken in July 2022. Groundwater levels have been recorded on a monthly basis and an additional reading on 23rd November following a period of particularly heavy rain.

The results are attached to this letter and monitoring of groundwater levels will continue on a monthly basis.

Yours faithfully



Rachel Foord BSc (Hons), MSc, MCSM, CGeol, FGS Director

Compass Geotechnical Limited

Head Office: 01455 213 311 Clacton Office: 01255 830 034 Fax: 01455 213 969 Email: rachel@compassgeotechnical.co.uk

Directors: R.M. Foord BSc, MSc, MCSM, C Geol, FGS

Consultants: E. J. Murray BSc, PhD, C Eng, FICE, C Geol, FGS, MaPS D. W. Rix BSc, MSc, DipArb, C Eng, MICE, MCIArb

www.compassgeotechnical.co.uk

January 2023

Groundwater Monitoring

SITE	Former Chambers Bus Garage, Bures

Date	Position	Depth to Water (m bgl)	Total Depth (m bgl)	Comments
	BHA	3.12	5.47	
14.02.22	BHB	3.18	5.87	
	BHC	3.15	5.79	
	BHD	3.16	5.90	
	WS2	3.27	3.49	
	BHA	2.79	5.47	
23.02.22	BHB	2.85	5.84	
23.02.22	BHC	2.83	5.78	
	BHD	2.84	5.90	
	BHA	2.76	5.50	
	BHB	2.83	5.74	
04.03.22	BHC	2.80	5.71	
	BHD	2.81	5.89	
	WS2	2.91	3.48	
	BHA	3.53	5.56	
	BHB	3.62	5.81	
06.07.22	BHC	3.59	5.76	
	BHD	3.61	5.96	
	WS2	-	3.54	40mm silt in base
01 00 00	BHE	4.67	6.44	
01.08.22	BHG	3.89	6.95	
	BHA	3.75	5.47	slight odour
	BHB	3.83	5.71	very slight odour
11 00 22	BHC	3.80	5.69	ÿ ű
11.08.22	BHD	3.81	5.88	
	BHE	4.69	6.38	
	BHG	3.89	6.83	
	ВНА	3.80	5.50	Slight odour
	BHB	3.86	5.72	very slight odour
02.09.22	BHC	3.83	5.69	, j
	BHD	3.83	5.89	
	BHE	4.72	6.38	
	BHG	3.92	6.84	
	WS2	dry	3.45	



January 2023

Date	Position	Depth to Water (m bgl)	Total Depth (m bgl)	Comments
	ВНА	3.80	5.48	Slight odour
	BHB	3.98	5.73	very slight odour
	BHC	3.94	5.69	, ,
28.09.22	BHD	3.95	5.89	
	BHE	4.83	6.36	
	BHG	4.03	6.84	
	WS2	dry	3.45	
	BHA	3.83	5.49	Slight odour
	BHB	3.98	5.78	very slight odour
	BHC	3.89	5.70	, ,
03.11.22	BHD	3.89	5.88	
	BHE	4.78	6.34	
	BHG	3.97	6.83	
	WS2	dry	3.45	
	ВНА	3.25	5.49	Slight odour
	BHB	3.34	5.72	very slight odour
23.11.22	BHC	3.32	5.70	, ,
After heavy	BHD	3.31	5.89	
rain	BHE	3.26	6.27	
	BHG	3.41	6.82	
	WS2	3.45	3.45	
	ВНА	3.31	5.49	Slight odour
	BHB	3.37	5.73	very slight odour
12.12.22	BHC	3.33	5.70	, ,
	BHD	3.35	5.89	
	BHE	4.20	6.26	
	BHG	3.42	6.82	
	WS2	3.45	3.46	
	ВНА	2.72	5.47	Very slight odour
	BHB	2.82	5.72	Slight odour
02.01.23	BHC	2.80	5.69	g 04041
	BHD	2.80	5.88	
	BHE	3.69	6.21	
	BHG	2.9	6.82	
	WS2	2.92	3.46	