

*Land to Rear of 45 West End, South Cave – Contaminated Land Assessment Phase 1  
Appendix D*

**A & F CONSULTING ENGINEERS LLP**

**Description: - Photographs**

**Date : -**

**21 February 2024**



**A – showing entrance/access to the site (land to the rear of 45 West End, South Cave) looking south west (from West End Farm Close)**



**B – showing shared entrance/access to the site looking north east**

*Land to Rear of 45 West End, South Cave – Contaminated Land Assessment Phase 1  
Appendix D*



**C – showing Plot 1 looking south east (previous garden/farm yard)**



**D – showing Plot 2 looking north west (previous garden/farm yard)**

*Land to Rear of 45 West End, South Cave – Contaminated Land Assessment Phase 1  
Appendix D*



**E – Plot 2 showing rubble heap looking east (building rubble)**



**F – Typical rubble heap waste (brick, stone, block, plastic & plastic string – baler band)**

*Land to Rear of 45 West End, South Cave – Contaminated Land Assessment Phase 1  
Appendix D*



**G – Typical rubble heap waste (stone, soil & wire mesh)**



**H – Typical rubble heap waste (block, vegetation & corrugated steel roof piece)**

*Land to Rear of 45 West End, South Cave – Contaminated Land Assessment Phase 1  
Appendix D*



**I – Typical scattered wastes (windblown, domestic, timber gate & gardening)**



**J – Plot 2 rubble heap & northern boundary view (looking north west)**

*Land to Rear of 45 West End, South Cave – Contaminated Land Assessment Phase 1  
Appendix D*



**K – Plot 1 old garden area – 43 West End behind boundary fence (looking south)**



**L – Plot 1 old garden area with concrete access - looking west (note vegetation)**

*Land to Rear of 45 West End, South Cave – Contaminated Land Assessment Phase 1  
Appendix D*



**M – Old Photograph showing previous outbuildings & site activities (~2005)**