



Photos 2: Bathroom window to be replaced




Bathroom Window (side of property) – view from Yarrow Gardens



Zoom view from Yarrow Gardens to confirm that window is not visible from public elevations

Zoom view from Yarrow Gardens Lane (private, unadopted access road)



Zoom view showing style and deterioration



Internal view showing style

