


REFERENCE # PA24/00723

CURRENT OLO CONSERVATORY




windows currently have wood timber that has severe rotting

Scale 1:50 cm

elevation drawing of existing elevations drawn to a scale of 1:50 cm metric

STRUCTURE IS AT GROUND LEVEL



Scale bar 1:50