








Dilapidated existing garage

Rusty corrugated tin



NOTES:

Client
H Englefield and Son
Job Title
Replacement Garage



Scale
1 in 100 A3
Drawn by
Nicholas Pike
Date 14/03/2024

Drawing Title
Existing Elevations

Drg No.
E3

Rev
1