



View looking south, window E4 on left

Item 10.17 Window E4 head: cut out bed joint above the south jamb in 3rd course above window head springing level, insert stitch 500mm long as specification in item 10.8

Item 10.16 rake out the cracked bed joint south of window E4 3no courses below the ceiling joist bearings provisional 3500mm length on wall arc, pack with hydraulic lime mortar NHL5 and point up to surface, brush up when set

Client:	Lincolnshire County Council		
Job Title:	Burgh le Marsh Windmill: repairs		
Drawing Title:	4 th floor internal walling repairs		
Scale:	NTS @ A3	Drawn By:	PEO
		Date:	November 2023
Job Number:	6700/3	Drawing Number:	5



Unit 12, Park Farm Business Centre, Fomham St Genevieve, Bury St Edmunds, IP28 6TS
01284 760421 info@whitworth.co.uk www.whitworth.co.uk

NOTE:
Do not scale from this drawing. Confirm all dimensions on site. Refer any discrepancies to the Architect before work is put in hand. Read this drawing in conjunction with the relevant sections of the specification, schedule of works and other drawings.

This drawing is copyright of whitworth