

Richard Backhouse
111 The Mall, SN1 4JE
rwbackhouse1@gmail.com
07515 888 829



Wall to be replaced

Point **B** on map

Location of Figure 3
showing bulging wall
Point **A** on map

Figure 1 View of 111 The Mall from across the road

Richard Backhouse
111 The Mall, SN1 4JE
rwbackhouse1@gmail.com
07515 888 829

Tree 1: (cedar ?) to be felled: trunk diameter = 43cms

Tree 2: (laurel bush (?)) to be felled: trunk diameters = 15-20cms

Tree 3: (cherry plum) to be felled: trunk diameter = 22cms

Laurel to be cut back




Figure 2: View of 111 The Mall from across the road with trees to be felled

Richard Backhouse
111 The Mall, SN1 4JE
rwbackhouse1@gmail.com
07515 888 829

Bulge in grey sandy wall at right hand side of Figures 1 & 2: note displacement from vertical at top of wall (c. 10cms). This is point **A** on map

Red brick wall in foreground is vertical wall for 66 Westlecot Road

Bulging out of 111 wall aligns with roots of Large Tree 1 (cedar ?) and Tree 2 shown on Figure 2. Note branches overhang the pavement



Figure 3 Displacement of wall from tree roots

Richard Backhouse
111 The Mall, SN1 4JE
rwbackhouse1@gmail.com
07515 888 829

VIEW FROM IN GARDEN
OF 111 THE MALL

Tree 1 is the major tree to be felled
Diameter = 43cms 1.5m above
ground

This is the tree behind the most
prominent bulge in the wall




Tree 1: (cedar ?)

Tree 2: (laurel bush?)
In background

Figure 4 Tree 1 and 2 to be felled

Richard Backhouse
111 The Mall, SN1 4JE
rwbackhouse1@gmail.com
07515 888 829

VIEW FROM IN GARDEN
OF 111 THE MALL



Tree 1: (cedar ?)

Tree 2: (laurel bush?)

Figure 5 Close-up of trees 1 and 2

VIEW FROM IN GARDEN
OF 111 THE MALL

Richard Backhouse
111 The Mall, SN1 4JE
rwbackhouse1@gmail.com
07515 888 829

Edge of wall at north
end of property.
Point **B** on map

Tree 3: cherry plum

Figure 6 Tree 3

