

Appendix 2 – Screening Assessment Form (Version 10.3)

If you are undertaking a small development (i.e. one house in a garden) this Screening Assessment Form can be used as a basic contamination assessment, which fulfils the requirements of the 'Existing Use' section of the planning application form. This form may be used in other circumstances at the discretion of the Local Planning Authority, but please check with them first.

This Screening Assessment Form is not suitable for larger housing developments, allotments, schools, nurseries, children's play areas, playing fields, or if there has been a past industrial use on or adjacent to the land. In these instances, you will need to submit a Phase 1 Report (Preliminary Risk Assessment) and if appropriate, subsequent Phase 2 (Site Investigation and Risk Assessment), Phase 3 (Remediation Strategy) and Phase 4 (Verification) Reports.

NOTE: Failure to provide the required information at this stage may result in a delay in the application process and the imposition of planning conditions relating to land contamination.

If at any point when completing the form you suspect there is a likelihood that contamination may exist on the site (or on an adjacent site) which could affect the proposed use, it is strongly advised that you contact the Council's Contaminated Land Officer before proceeding, as your findings may necessitate the submission of a more detailed Phase 1 Report.

Please complete this form in **BLOCK LETTERS** and submit with photographs to the Local Planning Authority with your completed Planning Application Form.

APPLICANT / AGENT DETAILS

	Applicant	Agent
Full Name	John C Hammond	Peter Gidney
Address	CaleyFarmhouse 1 Station Road Heacham, King's Lynn PE31 7HQ	West Hall Cottage, Vicarage Lane, Gayton, Kings Lynn, PE32 1PD
Telephone	██████████	██████████
Email	████████████████████	████████████████████

DEVELOPMENT DETAILS

Site Name	New Dwelling and Garage			
Site Address	1 Kenwood Road, Heacham, King's Lynn., PE31 7DD			
Site Grid Reference	Easting	567926	Northing	337576

SITE DESCRIPTION

Please provide a detailed description and photographs of the land being developed. Include details of the layout and ground covering, any evidence of former buildings or site activities, any evidence of made/filled ground, and any signs of subsidence or contamination (e.g. ground staining/discolouration, odours, vegetation distress/dieback).

Former Single Garage for one Lorry with space around.
 1 Derelict Garage corrugated Iron to be demolished if planning granted.
 Site is the only non-residential plot in the area.
 No liquids stored.
 Inert material
 Some old bricks-wood
 Earth and Sand.
 Temporary parking.
 No Asbestos.
 No Fuel
 No Oil
 No filled ground.
 Vegetation shows no sign of stress.
 No subsidence.
 No odours.
 In applicant's family for generations.

SITE HISTORY, LAND AND BUILDING USE

Please undertake a complete historical map review dating back to the mid/late 1800's, to provide a description of the previous uses(s) of the site and immediate surrounding area. *Historical maps are available to view online and possibly at local libraries.*

	Domestic	Agricultural	Commercial	Industrial	Other (give details)
Proposed land use (tick all that apply)	√				
Current land use (tick all that apply)			√		Derelict building Store
Past land use – last 150 years (tick all that apply)	√	√			

NOTE: If the site has a past or current industrial use, this Screening Assessment Form should not be used and you will need to submit a Phase 1 Report (Preliminary Risk

Assessment) instead.

If the past land use has changed, please give date of change(s) (please use category types from the previous table).	From	To	Land Use
		2014	Building-store -yard

What have the existing buildings onsite been used for? (please state if applicable)	Parking of 1 Lorry	
Are any of these buildings constructed from suspected asbestos containing material? (including cement sheets, gutters, drainpipes, lagging and insulation)	No Corrugated Iron	
If any buildings are constructed from suspected asbestos containing material, please state whether an asbestos survey has been carried out and whether the material will be removed as part of the development.	Inspection shows no asbestos.	

Have any fuels/chemicals been stored onsite?		No <input type="checkbox"/>
Have there been any fuel/chemical spills or leaks?		No <input type="checkbox"/>
If 'Yes' to either of the above, please state fuel/chemical, storage method and location, and details of any spillages.		

Have there been any pollution incidents, either reported or unreported? For information please refer to Environmental Pollution Incidents on data.gov.uk	Reported		Unreported	
		No <input type="checkbox"/>		No <input type="checkbox"/>

Provide details of any surface water present onsite (including drains, ponds, streams and rivers).	None
Provide details of any groundwater or surface water abstractions (including wells and boreholes).	N/A

WASTE DISPOSAL ACTIVITIES

Landfill sites can sometimes contaminate surrounding land. For more information and to check if any current or historical landfill sites are located near your site, please refer to the Environment Agency's section on data.gov.uk or contact the Council's Contaminated Land Officer.

Have any waste disposal activities (including the burning of waste) been carried out onsite?		No <input type="checkbox"/>
Have any waste disposal activities been carried out on surrounding land within 250 metres of the site?		No <input type="checkbox"/>
Is there any evidence of demolition activities (e.g. rubble) onsite?	Not demolition on site - stored only	No <input type="checkbox"/>
If 'Yes' to any of the above, please provide details.		



Entrance from Kenwood Road



Rear



1800'S



EARLY OS