



CHURCH EXISTING EXTERNAL PHOTOGRAPHS



1.



2.



3.



4.

- 1 View of stone ornament
- 2 View of North wall with overgrowth
- 3 View of South Elevation with extensive overgrowth
- 4 View of existing courtyard (West Elevation)