
This information relates only to 'Significant Hazards' identified on this drawing and is to be read in conjunction with the Designer's Risk Assessment Register.



Dome camera fixing detail

50 0 50 100 150 200 250 Scale 1:5@A3 
 Job No
 Origin
 Volume
 Level
 Type
 Role
 Number
 Rev

 W0904
 WW
 ZZ
 ZZ
 DT
 A
 0318

Drawing Title
Dome Camera Wall Fixing

Client's Name Rengen 
 Drawn
 Checked
 Date

 SMc
 AB
 15/03/24

 Job Title
 AB
 15/03/24

10-12 Cave Street, Bristol

PRELIMINARY

