MONITORING

LEVEL MONITORING for Subsidence Management Services

37 West End, March Amby Cottage, Cambridgeshire, PE15 8DN

Client:	Subsidence Management Services	
Client Contact:	Nigel Buxton	
Claim Number:	700019942	
Client Reference:	IFS-LBG-SUB-22-0104134	
Policy Holder:	Mrs Pauline Wright	
Report Date:	22 January 2024	
Our Ref:	M20539	

MONITORING

Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

Date	1	2	3
11/02/2023	10.0000	9.9887	9.9639
21/04/2023	10.0000	9.9894	9.9636
21/06/2023	10.0000	9.9889	9.9630
01/09/2023	10.0000	9.9885	9.9632
10/11/2023	10.0000	9.9873	9.9611
16/01/2024	10.0000	9.9879	9.9622

Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.





SubsNetuk

MONITORING

Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.





SubsNetuk

FRONT

Site Visit Notes

Datum is level station 1, it has an assumed value of 10,0000m. No suitable remote datum available. If this is not suitable, please advise if a deep datum is required. Relative Survey.

MONITORING