



4041



John Lamb
Earthworks Testing Ltd
69 High Street
Dodworth
Barnsley
South Yorkshire
S75 3RQ

i2 Analytical Ltd.
7 Woodshots Meadow,
Croxley Green
Business Park,
Watford,
Herts,
WD18 8YS

e: ops@earthworkstesting.co.uk

t: 01923 225404
f: 01923 237404
e: reception@i2analytical.com

Analytical Report Number : 23-45940

Project / Site name:	Bingley	Samples received on:	19/07/2023
Your job number:	C1021	Samples instructed on/ Analysis started on:	19/07/2023
Your order number:	SC015	Analysis completed by:	28/07/2023
Report Issue Number:	1	Report issued on:	28/07/2023
Samples Analysed:	5 soil samples		



Signed: _____

Anna Goc
PL Head of Reporting Team
For & on behalf of i2 Analytical Ltd.

Standard Geotechnical, Asbestos and Chemical Testing Laboratory located at: ul. Pionierów 39, 41-711 Ruda Śląska, Poland.

Accredited tests are defined within the report, opinions and interpretations expressed herein are outside the scope of accreditation.

Standard sample disposal times, unless otherwise agreed with the laboratory, are :	soils	- 4 weeks from reporting
	leachates	- 2 weeks from reporting
	waters	- 2 weeks from reporting
	asbestos	- 6 months from reporting

Excel copies of reports are only valid when accompanied by this PDF certificate.

Any assessments of compliance with specifications are based on actual analytical results with no contribution from uncertainty of measurement. Application of uncertainty of measurement would provide a range within which the true result lies. An estimate of measurement uncertainty can be provided on request.



Analytical Report Number: 23-45940
 Project / Site name: Bingley
 Your Order No: SC015

Lab Sample Number	2753606			2753607			2753608			2753609			2753610		
Sample Reference	C1021			C1021			C1021			C1021			C1021		
Sample Number	/2			/3			/4			/5			/6		
Depth (m)	None Supplied			None Supplied			None Supplied			None Supplied			None Supplied		
Date Sampled	18/07/2023			18/07/2023			18/07/2023			18/07/2023			18/07/2023		
Time Taken	1700			1700			1700			1700			1700		
Analytical Parameter (Soil Analysis)	Units	Limit of detection	Accreditation Status												
Asbestos in Soil	Type	N/A	ISO 17025	Not-detected	Not-detected	Not-detected	Not-detected	Not-detected	Not-detected	Not-detected	Not-detected	Not-detected	Not-detected	Not-detected	
Asbestos Analyst ID	N/A	N/A	N/A	EWS	EWS	EWS	EWS	EWS	EWS	EWS	EWS	EWS	EWS	EWS	

U/S = Unsuitable Sample I/S = Insufficient Sample ND = Not detected



Analytical Report Number : 23-45940
Project / Site name: Bingley

Water matrix abbreviations:

Surface Water (SW) Potable Water (PW) Ground Water (GW) Process Waters (PrW) Final Sewage Effluent (FSE) Landfill Leachate (LL)

Analytical Test Name	Analytical Method Description	Analytical Method Reference	Method number	Wet / Dry Analysis	Accreditation Status
Asbestos identification in soil	Asbestos Identification with the use of polarised light microscopy in conjunction with dispersion staining techniques.	In house method based on HSG 248	A001-PL	D	ISO 17025

For method numbers ending in 'UK or A' analysis have been carried out in our laboratory in the United Kingdom (WATFORD).

For method numbers ending in 'F' analysis have been carried out in our laboratory in the United Kingdom (East Kilbride).

For method numbers ending in 'PL or B' analysis have been carried out in our laboratory in Poland.

Soil analytical results are expressed on a dry weight basis. Where analysis is carried out on as-received the results obtained are multiplied by a moisture correction factor that is determined gravimetrically using the moisture content which is carried out at a maximum of 30oC.

Unless otherwise indicated, site information, order number, project number, sampling date, time, sample reference and depth are provided by the client. The instructed on date indicates the date on which this information was provided to the laboratory.