



HAZARDS AND RISKS WARNING

The items listed below indicate known hazards or areas of significant risk.

This is a "new build" construction. No Asbestos Containing Materials have been specified.

Prior to commencing any ground works, refer to the site investigation report for information on any known hazardous materials present.

Rev	Date	Description	By
REVISIONS			

This map is reproduced from Ordnance Survey material with the permission of Ordnance Survey on behalf of the controller of her Majesty's Stationery Office © Crown Copyright.

Unauthorised reproduction infringes Crown Copyright and may lead to prosecution or civil proceedings.
Fife Council 100023385 (2013)

Drawing Status :

PLANNING



ASSETS, TRANSPORTATION AND ENVIRONMENT:
PROPERTY SERVICES

Senior Manager: ALAN PAUL
Bankhead Central, 1 Bankhead Park, Glenrothes, Fife, KY7 6GH
Tel: (01592) - 583238 E-mail: Property.Clientgroup1@fife.gov.uk

Contract Administrator :

PAULINE MARTIN

Drawn By : P.M. Date : JUN. '23 Scale : 1 : 1250 Checked By :

Property Address :

**ST ANDREWS TOWN HALL
QUEENS GARDENS, ST ANDREWS**

Project Title :

CHAMBERS REPAIRS

Drawing Title :

LOCATION PLAN

Computer Reference :

Works Request Number : **CS7602318** UPRN : **00041300**

Drawing Number : **01** Revision :