



HAZARDS AND RISKS WARNING

The items listed below indicate known hazards or areas of significant risk.

This is a "new build" construction. No Asbestos Containing Materials have been specified.

Prior to commencing any ground works, refer to the site investigation report for information on any known hazardous materials present.

This map is reproduced from Ordnance Survey material with the permission of Ordnance Survey on behalf of the controller of Her Majesty's Stationary Office © Crown copyright.

Unauthorised reproduction infringes Crown copyright and may lead to prosecution or civil proceedings.

By	Date	Description
Fife Council	100023385	REPAIRS

**ASSETS, TRANSPORTATION AND ENVIRONMENT:
PROPERTY SERVICES**

Senior Manager: ALAN PAUL

Bankhead Central, 1 Bankhead Park, Glenrothes, Fife, KY7 6GH
Tel: (01592) - 583238 E-mail: Property.Clientgroup1@fife.gov.uk

Drawing Status :

PLANNING

Contract Administrator :

PAULINE MARTIN

Drawn By :	Date :	Scale :	Checked By :
P.M.	JUN. '23	1 : 200	

Property Address :

**ST ANDREWS TOWN HALL
QUEENS GARDENS, ST ANDREWS**

Project Title :

CHAMBERS REPAIRS

Drawing Title :

SITE PLAN

Computer Reference :

Works Request Number :	UPRN :
CS7602318	00041300

Drawing Number :	Revision :
02	

SCALE BAR 1:200

0 5 10 20 40m

A2