

**INFILTRATION SYSTEMS:
 TEST RESULTS**

In connection with the current/proposed planning application, this statement is to be included as part of the application certifying that percolation testing of sub-soil conditions has been undertaken. I understand and accept further testing may be necessary.

Location of Site	BRUAN
------------------	-------

NOTE:- A site plan showing the location of all holes is enclosed and all known private water supplies within 50 metres of the proposed soakaway area clearly identified on the plan.

Planning Application Reference		Grid Reference	
--------------------------------	--	----------------	--

Applicants Name: Address: Telephone Number:	JANE ESSEX
---	------------

Agent's Name (if applicable): Address: Telephone Number:	ALAN GOW THE YARD SORDALE HIGHLAND KW12 6XB 01847 831 120
--	---

	1 st Test	2 nd Test	3 rd Test	Average
Date of Test	17/03	18/03	18/03	
Pit A - Time for water to drain (Middle 150mm section of 300mm)	72mins	75mins	75mins	74mins
Pit B - Time for water to drain (Middle 150mm section of 300mm)	71mins	76mins	77mins	75mins

Water Table Depth from Ground Level	1.7m
Average Vp	30

NO WATER TABLE
 LARGE BOULDERS
 EXCAVATOR TOO SMALL
 TO REMOVE FROM PIT

I certify that the above results are an accurate record of the tests carried out in accordance with the Highland Council guidance notes.

I also confirm/certify the suitability of subsoil conditions for the disposal of effluent by means of an infiltration system at this location.

Signature of applicant/agent: _____ Date: 18/03/2024